

# MarGage 390

## Setting disc with tolerance class

| Diameter<br>mm | Order no. |
|----------------|-----------|
| 69             | 4717089   |
| 70             | 4717090   |
| 71             | 4717091   |
| 72             | 4717092   |
| 73             | 4717093   |
| 74             | 4717094   |
| 75             | 4717095   |
| 76             | 4717096   |
| 77             | 4717097   |
| 78             | 4717098   |
| 79             | 4717099   |
| 80             | 4717100   |
| 81             | 4717101   |
| 82             | 4717102   |
| 83             | 4717103   |
| 84             | 4717104   |
| 85             | 4717105   |
| 86             | 4717106   |
| 87             | 4717107   |
| 88             | 4717108   |
| 89             | 4717109   |
| 90             | 4717110   |
| 91             | 4717111   |
| 92             | 4717112   |
| 93             | 4717113   |
| 94             | 4717114   |
| 95             | 4717115   |
| 96             | 4717116   |
| 97             | 4717117   |
| 98             | 4717118   |
| 99             | 4717119   |
| 100            | 4717120   |

# MarGage 390

## Setting disc with tolerance class

### FEATURES

- Wear-resistant special gage steel
- Hardened and lapped
- Manufacturing tolerance:  
 $\pm 1/2$  IT 2
- Uncertainty of the actual size:  
 $1/2$  IT 1
- The ideal setting standards for  
the Marameter 840 F and 300 P  
indicating snap gage families
- Gradation 0.001 mm
- Please specify diameter  
when placing order

| Ø<br>mm     | Order no. |
|-------------|-----------|
| 10.001 –14  | 4719900   |
| 14.001 –20  | 4719901   |
| 20.001 –30  | 4719902   |
| 30.001 –40  | 4719903   |
| 40.001 –50  | 4719904   |
| 50.001 –60  | 4719905   |
| 60.001 –70  | 4719906   |
| 70.001 –80  | 4719907   |
| 80.001 –90  | 4719908   |
| 90.001 –100 | 4719909   |

