Functions	Horizontal
ORIGIN (ABS-Zero)	
Low voltage alarm	(4)
Data output	
Specifications	
Digital step	0,01 mm

Unlimited

0,01 mm

Optional accessories

Max. response speed

Repeatability

No.	Description
05CZA624	Digimatic Cable with Data Button IP Type, 1m, Caliper Type
05CZA625	Digimatic Cable with Data Button IP Type, 2m, Caliper Type
02AZD790A	U-WAVE-T Connection Cable A, with Data Button IP Caliper Type
06AFM380A	USB Input Tool Direct (Digimatic USB), Digi/Digi2, With Data Button IP Caliper Type

Consumable spares

No.		Description				
	938882	Battery SR44 1.5V				

Horizontal ABSOLUTE Scale Coolant Proof IP66

Horizontal

You can use this scale unit in adverse environments with water and cutting oil due to it new detection method (electromagnetic induction).



- Specially designed output cables are developed to maintain the water resistant structure.
- You will have no overspeed error since the ABSOLUTE scale does not depend on counting scale graduations.
- Once an absolute zero (origin) point is set, the Digimatic Scale Unit shows the absolute distance from this point when it is powered on, rather than "0".



572-601

o,	а	7	c
	S		L

No.	Range [mm]	Accuracy	L1 [mm]	L2 [mm]	Mass [g]
572-600	0 - 100	0,03 mm	209	185	390
572-601	0 - 150	0,03 mm	259	235	410
572-602	0 - 200	0,03 mm	311	287	430



